

Burlington, WA Corporate Laboratory (a)
1620 S Walnut St - Burlington, WA 98233 - 800.755.9295 • 360.757.1

Bellingham, WA Microbiology (b)

Portland, OR Microbiology/Chemistry (c) 9150 SW Pioneer Ct Ste W - Wilsonville, OR 97070 - 503.682.780

Corvallis, OR *Microbiology/Chemistry* (d)

Bend, OR *Microbiology* (e) 20332 Empire Blvd Ste 4 - Bend, OR 97701 - 541.639.8425



LEAD & COPPER RULE REPORT

Client Name: Mount Baker Water Association

PO Box 29465

Bellingham, WA 98228

System ID Number:

Lab Number: 046-69280

Sample Purpose: Investigative or Other

Sample Composition:

Approved By: bj

Authorized By: \((

Lawrence J Henderson, PhD Director of Laboratories, Vice President System Group Type:

System Name:

County:

Reference Number: 21-35989

Project: L & C 2021

Source Number:

Multiple Sources:

Date Received: 9/21/2021

Date: Reported: 9/28/21

Sample Type:

Sample Collected By:

Sampler Phone:

Lab Number	Date Collected	Site / Location	PRM#	Analyte Name	Result	Units	AL	SRL	METHOD	Lab	Analyzed	Comments
046-69280	9/21/2021	1 - 4768 Sand Rd	9	LEAD	ND	mg/L	0.015	0.001	200.8	а	9/24/21	
			23	COPPER	0.501	mg/L	1.3	0.005	200.8	а	9/24/21	
046-69281	9/17/2021	2 - 3195 Mt Baker	9	LEAD	ND	mg/L	0.015	0.001	200.8	а	9/24/21	
			23	COPPER	0.509	mg/L	1.3	0.005	200.8	а	9/24/21	
046-69282	9/17/2021	3 - 5455 Allison	9	LEAD	ND	mg/L	0.015	0.001	200.8	а	9/24/21	
			23	COPPER	0.228	mg/L	1.3	0.005	200.8	а	9/24/21	
046-69283	9/17/2021	4 - 5055 Sand	9	LEAD	ND	mg/L	0.015	0.001	200.8	а	9/24/21	
			23	COPPER	0.361	mg/L	1.3	0.005	200.8	а	9/24/21	
046-69284	9/17/2021	5 - 3492 Mt Baker	9	LEAD	ND	mg/L	0.015	0.001	200.8	а	9/24/21	
			23	COPPER	0.0117	mg/L	1.3	0.005	200.8	а	9/24/21	

NOTES:

SRL (State Reporting Level): indicates the minimum reporting level required by the Washington Department of Health (DOH).

AL Federal Action Levels are 0.015 mg/L for Lead and 1.3 mg/L for Copper under the Lead and Copper Rule for public water systems. A blank MCL value indicates a level is not currently established.

ND (Not Detected): indicates that the compound was not detected above the Specified Reporting Limit (SRL).

These test results meet all the requirements of NELAC, unless otherwise stated in writing, and relate only to these samples. If you have any questions concerning this report contact Lawrence J Henderson, PhD, Director of Laboratories, Vice President, at the toll-free phone number above.